`p_init()`	Check-in with PAPERS hardware
`p_exit(e)`	Check-out with PAPERS hardware, exit code e
`p_error(s)`	Print error message s, check-out, and exit